

Anyone out there fix vintage stereo receivers? I blew out the left channel in my "70"s vintage Marantz 2230 Stereo receiver. The left internal amp has blown after 45 years of ...

Personally, I would stick with the Marantz, the 2230 is I believe among some of their best units of the period. If your running it in stereo, quality wise the Marantz would sound better than the ...

The guy selling it was the same guy who serviced it and he does a very good job. Recapped the power supply, replaced transistors etc and lights. This was my first real vintage stereo and I ...

I've seen plenty of melted and discoloured bulb housings from fully functional receivers to know that time and exposure to heat deforms them. Marantz mostly because they used plastic for ...

The Marantz 2230 is a capacitor coupled design that would definitely fit the OP"s statement of "Looking for warmth and color at lower dB"s" I have the amp section of the 2230 ...

Well, I did another data dive and compiled a fairly comprehensive list of 99% of the transistors and diodes used in 70"s era Marantz stereo integrated amps and receivers.

Building a case for Marantz 2230 I'm planning to build a case for my 2230. I have some 11-1/2" wide x 1" rough sawn walnut, so I'll have to plane it down to 3/4" and edge glue a ...

Had a guy bring me a totally biffed matantz 2230 4 days ago. He had the wooden case for it. It looked like a piece of driftwood! It was in four pieces! I clamped it... using some quick set ...

Pretty sure I've got a blown output transistor on Marantz 2230. Voltages are strange on one side. Lots of distortion on that side. Checked mouser, digikey. No cross ...

Web: <https://goralskidwor.com.pl>